


SENZA 1 GW470-62

1



x1

2



x1

3



M8x20

x2

4



ϕ 4.8x13

x2

5



ϕ 5x40

x2

6



ϕ 20x ϕ 7

x2

7



ϕ 8x40

x2

8



ϕ 8x40

x2

9



ϕ 6x30

x2


10



ϕ 3.5x30

x2

11



S6

x1